

Safety Topic of the Month

RI-341: Hot Work and General Work Permits - Updates

Richmond Refinery

February 2011



Outline

- Purpose of RI-341 and the Recent Changes
- Ignition Source Permit Updates to RI-341
- Text Updates to RI-341
- Contacts for Questions
- Review of Near Losses and TOP Lessons Learned




Refinery Instruction 341

- RI-341 is the Refinery's policy regarding all Hotwork
- Changes were made to the Refinery Instruction following a Operational Excellence (OE) audit that occurred in 2010
 - The OE Audit found areas where the Richmond Refinery should be more clear on its policy surrounding Hotwork



Changes to RI-341 and the Ignition Source Permit

Changes were made to the wording of the Ignition Source Permit (MFG-7625) and to the wording of RI-341






© Chevron 2005 DOC ID



Ignition Source Permit Changes #1

A new checkbox reminding those filling out the permit to perform their Hazard Assessment needs to be checked



 If you want to go home safe every day, ensure that you account for all the hazards surrounding you. Try using some helpful tools such as the LPSA card, or the Hazard ID Wheel!





DOC ID



Ignition Source Permit Changes #2

Permit Extension is now only allowed for a "maximum of 6 consecutive days" and a section of the permit now requires the date where the "permit cannot be renewed past" date to be recorded.

No Hot work May Begin Until Restriction Requirements Are Met, Approval Signatures Are

Obtained And Permit is Fosted At the Job Site

PERMIT EXTENSION (for the period below only - maximum of 6 consecutive days)

This permit cannot be renewed past (Date):

 This section previously read "6 consecutive shifts" and has been modified to prevent confusion which could potentially create a dangerous environment.

© Chevron 2005 DOC ID 6



Ignition Source Permit Changes #3

The permit has been updated to include the Head Operator as having the ability to sign off on the non-open flame permits regarding the specified hotwork restrictions

Necessary restrictions specif'd (STL Open /HO Non-Open)

 It was important for contract companies and others not familiar with our processes to understand who is able to sign off open and non-open flame permits regarding the specified hot work restrictions

© Chevron 2005 DOC ID 7



RI-341 Text Changes

- Permit Retention:
 - <u>Operations</u> will now save the top copies of all <u>Non-Open</u>
 <u>Flame</u> Ignition Source Permits for one (1) year for the purpose of auditing the permit process (RI-341 Section 11.1)
 - Chevron Fire Department will continue to keep the top copy of <u>Open Flame</u> Ignition Source Permits
- Intrinsically Safe Clarifications:
 - RI-341 Section 4.6 now provides clarification to the wording regarding the limitations of use of non-intrinsically safe devices in Class 1, Division 1 areas and hazardous atmospheres
- Maximum Time Limit on the Ignition Source Permits
 - RI-341 Section 10.2 now clarifies that Ignition Source permits are not allowed to be renewed after six (6) consecutive days (formerly six consecutive shifts)



Questions?

If you have questions, please feel free to contact your area's Field Safety Coordinator



DOC ID





Near Loss ID	Date Occurred	Division 9	Short Description	Immediate Corrective Actions Taken	Potential Severity Class.	Location of Near
5243	1/5/11	Hydro - A Crew	F-1200 trip / 82Fl002	Operators responded using JOB Aid (LNC00QR.ja Respond to FSC fail-safe logic for F-1200)	Level 1	Rich Hydroproc essing RLOP LNC
5246	1/1/11	Oils Planning	Early butamer shutdown properly communicated	PenHex and Butamer Stabilizer shutdown was postponed 24 hours to prevent the NOV of the Title V permit.	Level 1	Rich Crack LPG/Alky Butamer Unit
5664	1/14/11	D&R - D Crew	K242 2nd stage safety started to lift and quit pumping	Steam was started to heat the fin fans incase salt had formed currently the temp is 122 deg Machine is now pumping	Level 1	
6038	1/15/11	Hydro - B Crew	Flaring during de- pressuring of the LNC	The line being used to depressure the LNC was blocked in.	Level 1	Rich Hydroproc essing RLOP RLOP Flare
		Shutdown Maintenance		Left the area and checked the monitor reading. The area was almost completely enclosed to prevent sparks from escaping. The area was		Rich Crack SRU 2300
6152	1/20/11	General Support B&S - B Crew		Reinforce the need for gauging in a timely manner	Level 1	Plant #3 SRU Rich B&S B&S Gen B&S Ctrl House
6211		Shutdown Maintenance General Support	gauge on T-3167 Hot slag fell on a piece of rope	to Inspection Company and Operations The rope was sprayed with a little water . Area was cleaned up and more fire blanket was put in place		Rich Crack SRU 2300 Plant #3 SRU
0211	1, 22, 11	Scherul Support	850 steam safety lifting in	Operations immediatly contacted Cogen to reduce 850 steam. Control board operator dumped 850# steam to 150# Steam to reduce pressure. Operation then found that 59PC851 wasn't	LC VCI I	Rich Crack
6450	1/25/11	Cracking - B Crew	FCC	opening None - not in position to identify driver or talk to	Level 1	FCC SGRU
6656	1/27/11	HES General	Green Card - Dangerous Driving in Cafeteria Parking Lot	them. Suggest lighting for crosswalk in parking lot and monitoring parking lot in morning to address unsafe behaviors	Level 1	Rich Admin Building

Report Near Losses Anonymously! Click here

10



Review TOP Lessons Learned

Learning from our past incidents will help us prevent them in the future. Please take a few minutes now to review the TOP lessons learned.

TOP Lessons Learned